



c

	TeO _x	Te on TeO _x	Al ₂ O ₃ passivated Te
Te ⁰	37.27	69.88	87.55
Sub-oxide	9.51	5.93	4.45
Te ⁴⁺	50.99	24.02	7.99
Te ⁶⁺	2.23	0.17	0.01
Te ⁰ : Te ⁴⁺	1 : 1.37	1 : 0.34	1 : 0.09