

Supplementary Information




Fig. S1 HRTEM image of S3 sample at two different magnification showing the presence of stacking faults.